


88-205 Removal and installation of molding on front bumper

Preliminary work:
Bumper removed (88-200)

Operation no. of operation texts and work units or standard texts
and flat rates:



P88-5349-57

- | | |
|-------------------------------|---|
| Clips (arrows, 14 each) | remove, install, installation tool
140 589 34 23 00. |
| Molding (1) | remove, install. |

Special tool

