



P33-2051-35

Check wishbone .....

- Visual inspection (for damage, corrosion and distortion).
- Push mandrel (018), 14 mm dia. length approx. 430 mm, through the wishbone holes in the direction of the arrow. The mandrel must be able to be pushed through, creating suction as it moves. If the mandrel does not align with the opposing rubber mount, replace wishbone.

Supporting joint of lower wishbone .....

Check (33-6170).

**Note**

It is no longer possible to use this method of measurement as of the production breakpoint of the rubber mount with steel sleeve (10/93). Perform visual inspection or comparison check with new part.